

**AUCTION
SERVICES****SPECIFICATIONS****1998 CASE/NEW HOLLAND 1840****Customer Owned Certified****SKID STEER LOADERS**

Inspection Number:	787564	Serial #:	JAF0222557
Date Created:	02/03/2012 10:40:57 AM CST	Engine Serial #:	N/A
Last Updated:	02/08/2012 03:41:02 PM CST	Transmission Serial #:	N/A
Originated By:	Melissa Ales	SMU/Hrs:	6480
Inspector:	N/A	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	ALBUQUERQUE, New Mexico, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client

Name: Company: Cat Auction Services
State: Unknown
Country: [Not Specified]

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Fair - FUEL CAP BROKEN		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Cab or Canopy	Fair - CANOPY DAMAGED		
Steps / Ladder	Fair - STEP BENT		
Grab Irons	Good		
Paint	Fair - SCRATCHES, NEEDS FILM		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

Notes

REPAIRS NEEDED. REST OF MACHINE IN GOOD APPEARANCE

Notes	REPAIR NEEDED, REST OF MACHINE IN GOOD AT LEAST
-------	---

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Horn	Fair - NOT WORKING		
Notes	REPAIR NEEDED		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Poor - KEY SWITCH SHORTED		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
Seat Belt	Fair - OLD AND NO TAGS		

	Condition - Remarks	Parts	Labor
Current O&MM	No - MISSING		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	RED, -37F		

	Condition - Remarks	Parts	Labor
Engine Supports	Good		
Air Cleaners	Fair - DIRTY		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

COOLING SYSTEM

	Condition - Remarks	Parts	Labor
Radiator	Good		
Hoses	Good		
Fan	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

ELECTRICAL, STARTING AND CHARGING SYSTEM

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good - BATTERY HAS CHARGE		

Wiring	Poor - ELECTRICAL PROBLEM, NO POWER TO START		
Lighting	Fair - LIGHTS DISCONNECTED		

TANDEMS/GEARS/BEARINGS/CHAINS

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		

HYDRAULICS

	Condition - Remarks	Parts	Labor
Tank	Good		
Hose Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

BUCKET

	Condition - Remarks	Parts	Labor
Cutting Edges	Fair		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Fair - LEFT SIDE CRACKED		
Quick Coupler	Good		

	Condition - Remarks	Parts	Labor
Bucket Capacity	62 IN.		

TIRES

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	GALAXY	14	46			
Left Front	GALAXY	13	43			
Right Rear	GALAXY	11	36			
Left Rear	GALAXY	6	20			
Tire Size	10X16.5					
Average Life Remaining	36%					

Caterpillar Confidential: Green. Copyright © 2012, Caterpillar Inc. All Rights Reserved.