

[«Back to Inspection Results](#)**AUCTION
SERVICES****SPECIFICATIONS****1998 MUSTANG MANUFACTURING 2070****Customer Owned Certified****SKID STEER LOADERS**

| | | | |
|---------------------------|--|--|-------------------|
| Inspection Number: | 788945 | Serial #: | SG980000712 |
| Date Created: | 02/16/2012 08:59:23 AM CST | Engine Serial #: | N/A |
| Last Updated: | 02/16/2012 11:40:20 AM CST | Transmission Serial #: | N/A |
| Originated By: | Shane Wilkinson | SMU/Hrs: | N/A |
| Inspector: | N/A | Last Scheduled Oil Sample: | N/A |
| Reviewer: | N/A | Last Cat Track System Inspection: | N/A |
| Salesman: | N/A | Last Preventative Maintenance: | N/A |
| Location: | ALBUQUERQUE, New Mexico, United States | Recommendation: | no recommendation |
| Asking Price: | N/A | Final Price: | N/A |

Condition**GENERAL APPEARANCE**

| | Condition - Remarks | Parts | Labor |
|--------------------------------------|------------------------------|-------|-------|
| Radiator Grill & Shroud | Good | | |
| Eng. Enclose Hood / Stack | Good | | |
| Fenders | Good | | |
| Fuel Tank | Good | | |
| Crankcase Guard / Battery Box | Good | | |
| Main Frame Welds | Good | | |
| Cab or Canopy | Fair - Front canopy damage | | |
| Steps / Ladder | Good | | |
| Grab Irons | Good | | |
| Paint | Fair - Scratches, needs film | | |

| | Condition - Remarks | Parts | Labor |
|--------------------------|--|-------|-------|
| S.O.S. Taken | No | | |
| Cleaning Required | No | | |
| Notes | Repairs needed, rest of machine in good appearance | | |

SAFETY ITEMS

| | Condition - Remarks | Parts | Labor |
|--------------|---------------------|-------|-------|
| Horn | Poor - Not working | | |
| Notes | Repairs needed | | |

GAUGES, OPERATOR STATION, CONSOLE

| | Condition - Remarks | Parts | Labor |
|---------------------|---------------------|-------|-------|
| Dash Console | Good | | |
| Meter | Good | | |

| | | | |
|--------------------------------|---|--|--|
| Gauges | Poor - Warning gauge cracked and fuel gauge not working | | |
| Switches | Good | | |
| Seat Cushion / Arm Rest | Good | | |
| Floor Boards | Good | | |
| EMS Panel / Warnings | Good | | |
| Hydraulic Controls | Good | | |
| Seat Belt | Fair - Old | | |

| | | | |
|-------------------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Current O&MM | No - Missing | | |
| Notes | Repairs needed | | |

ENGINE

| | | | |
|--------------------------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Oil Leaks | No | | |
| Blow By | No | | |
| Knocking | No | | |
| Compression in Radiator | Yes - Oil in radiator | | |
| Water in Oil | No | | |
| Fluid Levels OK? | No - Hydraulic oil low | | |

| | | | |
|------------------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Smoke (B/D/L/W) | Normal | | |

| | | | |
|------------------------------|---|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Operating Condition | Fair - Engine stalls due to travel always engaged | | |
| Turbocharger / Blower | Good | | |
| Fuel Injection System | Good | | |
| Governor | Good | | |
| Engine Supports | Good | | |
| Air Cleaners | Fair - Dirty | | |
| Exhaust / Muffler | Good | | |
| Belts / Pulleys | Good | | |
| Notes | Repairs needed, engine runs | | |

COOLING SYSTEM

| | | | |
|-------------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Radiator | Good | | |
| Hoses | Good | | |
| Water Pump | Good | | |
| Fan | Good | | |
| Fan Drive | Good | | |
| Notes | Cooling system works | | |

| | | | |
|--------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Leaks | No | | |

| | Condition - Remarks | Parts | Labor |
|--------------------|--|-------|-------|
| Batteries / Cables | Good | | |
| Starter | Good | | |
| Alternator | Good | | |
| Wiring | Good | | |
| Lighting | Fair - Rear flood broken off | | |
| Notes | Repairs needed, rest of electrical working | | |

TANDEM/GEARS/BEARINGS/CHAINS

| | Condition - Remarks | Parts | Labor |
|---------------------|---|-------|-------|
| Front Axle | Good | | |
| Rear Axle | Good | | |
| Travel Motors | Poor - Noted below | | |
| Travel Pumps | Poor - Noted below | | |
| Travel Controls | Poor - Travel engaged, machine drives circles | | |
| Lines / Linkages | Poor - Noted above | | |
| Operating Condition | Poor - Noted above | | |

HYDRAULICS

| | Condition - Remarks | Parts | Labor |
|---------------------|---------------------------|-------|-------|
| Operating Condition | Good | | |
| Tank | Good | | |
| Pumps & Valves | Good | | |
| Hose Lines | Good | | |
| Tilt Cylinder | Good | | |
| Lift Cylinders | Good | | |
| Notes | Hydraulic systems operate | | |

| | Condition - Remarks | Parts | Labor |
|-------|---------------------|-------|-------|
| Leaks | No | | |

BUCKET

| | Condition - Remarks | Parts | Labor |
|------------------------|---------------------|-------|-------|
| Cutting Edges | Fair - Have wear | | |
| Bucket Bottom | Good | | |
| Bucket Sides | Good | | |
| Bucket Linkage | Good | | |
| Loader Pins & Bushings | Good | | |
| Loader Frame | Good | | |
| Quick Coupler | Good | | |

| | Condition - Remarks | Parts | Labor |
|-----------------|---------------------|-------|-------|
| Bucket Capacity | 74" | | |

TIRES

| | | Tread | | | | |
|--|--|-------|--|--|--|--|
| | | | | | | |

| | Make / Serial# | Depth in 1/32" | % Life Remaining | Recapped | Tread Cuts/Chunks | Side Cuts Section |
|-----------------------------------|-----------------------|---------------------------|-----------------------------|-----------------|------------------------------|------------------------------|
| Right Front | Armour | 12 | 40 | | | |
| Left Front | Armour | 15 | 50 | | | |
| Right Rear | Titan | 16 | 53 | | | |
| Left Rear | Samson | 13 | 43 | | | |
| Tire Size | 12-16.5 | | | | | |
| Average Life Remaining | 46 percent | | | | | |

Caterpillar Confidential: Green. Copyright © 2012, Caterpillar Inc. All Rights Reserved.