

[«Back to Inspection Results](#)**AUCTION
SERVICES****SPECIFICATIONS****FORD / NEW HOLLAND 1920****Customer Owned Certified****BACKHOE LOADERS**

Inspection Number:	789371	Serial #:	UP25014
Date Created:	02/20/2012 01:56:45 PM CST	Engine Serial #:	N/A
Last Updated:	02/20/2012 02:56:29 PM CST	Transmission Serial #:	N/A
Originated By:	Shane Wilkinson	SMU/Hrs:	1846
Inspector:	N/A	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	ALBUQUERQUE, New Mexico, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Description

Ford farm tractor with front bucket and rear PTO/3 point hitch.

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Differential Supports	Good		
Cab or Canopy	Good		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		
Notes	Machine in good appearance/condition		

SAFETY ITEMS

Notes	Safety items in place and working
--------------	-----------------------------------

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Seat Cushion / Arm Rest	Fair - Seat cushion cracking; Seat will not adjust		
Floor Boards	Good		

	Condition - Remarks	Parts	Labor
Current O&MM	No - Missing		
Notes	Repairs needed, rest of operator controls are working		

	Condition - Remarks	Parts	Labor
Fuel Level	75 percent		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Red, +15F		
Oil Pressure (H/L/N)	normal		
Smoke (B/D/L/W)	White/blue		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Fair - Cracking		
Notes	Repairs needed, rest of engine is running good		

COOLING SYSTEM

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		

Water Pump	Good		
Fan	Good		
Fan Drive	Good		
Belts / Pulleys	Good		
Notes	Cooling system is working		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Lighting	Fair - Hazards/turn: right wire and left light broken; Floods: Left rear broken off		
Notes	Repair needed, rest of electrical is working		

————— TRANSMISSION —————

	Condition - Remarks	Parts	Labor
Case	Good		
Controls	Good		
Seals	Good		
Torque Converter	Good		
Universal Joints	Good		
Temp / Pressure Gauges	Good		
Lines / Fittings	Good		
Transmission - Reverse Shifts	Good		
Pump	Good		
Cooler	Good		
Transmission - Forward Shifts	Good		
Operating Condition	Good		

	Condition - Remarks	Parts	Labor
Transmission - Noisy	No		
Leaks	No		
Notes	Transmission shifting all gears forward/reverse, working good		

————— STEERING —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Steering Linkage	Good		
Tie Rods / Rod Ends	Good		
Steering Valves / Pumps	Good		

Steering Cylinder	Fair - Cylinder leak		
Lines / Fittings	Good		
Hand Metering Unit	Good		
Notes	Repair needed, rest of steering system is working good		

———— BRAKE ————

	Condition - Remarks	Parts	Labor
Brake Linkage	Good		
Pedal	Good		
Parking Brake	Good		
Notes	Service and parking brakes are holding and working		

	Condition - Remarks	Parts	Labor
Leaks	No		

———— FINAL DRIVES ————

	Condition - Remarks	Parts	Labor
Wheel Lugs & Rims	Good		
Rear Axle	Fair - Right side leak		
Front Axle	Fair - Can not disengage 4 wheel drive		
Trunion	Good		
Differentials	Good		
Notes	Repairs needed, rest of differentials are working good		

	Condition - Remarks	Parts	Labor
Leaks	Yes - Noted above		

———— HYDRAULICS ————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Lift Cylinders	Good		
Tilt Cylinder	Fair - Left cylinder leak		
Hose Lines	Fair - Right side hose leak		
Pumps & Valves	Good		
Control Linkage	Good		
Notes	Repair needed, rest of hydraulic system is working good		

	Condition - Remarks	Parts	Labor
Leaks	Yes - Noted above		

———— BUCKET ————

	Condition - Remarks	Parts	Labor
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Bucket Linkage	Good		

Bucket Floor	Fair - Floor bent and has no cutting edges		
Notes	Repair needed, rest of bucket in good condition		

————— **TIRES** —————

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	Harvest King	32	95			
Left Front	Harvest King	32	95			
Right Rear	Firestone	32	95			
Left Rear	Firestone	32	95			
Tire Size	Front 8-16; Rear 14.9-24					
Average Life Remaining	95 percent					
Notes	Rear tires have dry rot					

Caterpillar Confidential: Green. Copyright © 2012, Caterpillar Inc. All Rights Reserved.